

# Boral Cement Wauchope - POELA Act 2011 Monitoring Data

Environmental Protection Licence No. 1503

**Record updated on: 24 November 2023**

*Note: The Wauchope site is only required to monitor for noise annually, as such this report will only be updated annually.*

## 1. Noise monitoring

The 2023 Noise Monitoring Report by Muller Acoustic Consulting was finalised on 10 November 2023. Attended noise measurements were undertaken on Wednesday 1 November 2023 at the one EPL location and two alternative locations with depot noise contributions compared against the relevant criteria.

The assessment identified that noise emissions generated by the Boral Cement Wauchope site complied with the relevant noise criteria in the EPL at all assessed residential receivers.

EPL Location	Description	LAeq(15min) dBA Limit	LAeq(15min) 1/11/2023
EPL 2	19 Wallace St	55	53
ATT1 (not on EPL)	Cnr Wallace & Webb St	NA	<50
ATT2 (not on EPL)	26 Randall St	NA	<50

A copy of the Noise Monitoring Assessment (MAC201193-01RP4) prepared by Muller Acoustic Consulting is available on request.

## 2022 Noise Assessment

The 2022 Noise Monitoring Report by Muller Acoustic Consulting was finalised on 31 October 2022. Attended noise measurements were undertaken on Wednesday 19 October 2022 at the one EPL location and two alternative locations with depot noise contributions compared against the relevant criteria. The assessment identified that noise emissions generated by the Boral Cement Wauchope site complied with the relevant noise criteria in the EPL at all assessed residential receivers.

EPL Location	Description	LAeq(15min) dBA Limit	LAeq(15min) 19/10/2022
EPL 2	19 Wallace St	55	53
ATT1 (not on EPL)	Cnr Wallace & Webb St	NA	<50
ATT2 (not on EPL)	26 Randall St	NA	<50



**Building  
something  
great**

## 2021 Noise Assessment

The second Annual Noise Monitoring Report by Muller Acoustic Consulting was finalised on 29 November 2021. Attended noise measurements were undertaken on Wednesday 17 November 2021 at the one EPL location and two alternative locations with depot noise contributions compared against the relevant criteria. The assessment identified that noise emissions generated by the Boral Cement Wauchope site complied with the relevant noise criteria in the EPL at all assessed residential receivers.

EPL Location	Description	LAeq(15min) dBA Limit	LAeq(15min) 17/11/2021
EPL 2	19 Wallace St	55	51
ATT1 (not on EPL)	Cnr Wallace & Webb St	NA	<50
ATT2 (not on EPL)	26 Randall St	NA	<50

## 2020 Noise Assessment

The first Annual Noise Monitoring Report by Muller Acoustic Consulting was finalised on 5 November 2020. Attended noise measurements were undertaken on Wednesday 30 September 2020 at the one EPL location and two alternative locations with depot noise contributions compared against the relevant criteria.

The assessment identified that noise emissions generated by the Boral Cement Wauchope site complied with the relevant noise criteria in the EPL at all assessed residential receivers.

EPL Location	Description	LAeq(15min) dBA Limit	LAeq(15min) 30/09/2020
EPL 2	19 Wallace St	55	51
ATT1 (not on EPL)	Cnr Wallace & Webb St	NA	<50
ATT2 (not on EPL)	26 Randall St	NA	<50

**REPORT ENDS**